Sanitized - Approved For Release : CIA-RDP33-02415A000500030018-3

| TRANSM | ITTAL SLIP | DATE | | |
|--|------------|------|-----------|--|
| TO: | | | | |
| ROOM NO. | BUILDING | | | |
| REMARKS: | | | | |
| Thank you for the attached. I wonder if our current problems with | | | | |
| stability of the aircraft with the modi- | | | | |
| fied ECM pod and reflection from the pod on System XII are being passed to Colonel Geary for relay to SAC as solutions become apparent or as the problem assumes new dimensions. Please let me know. | | | | |
| C | | | | |
| MP | | | | |
| FROM: | DAD/C | SÅ | | |
| ROOM NO. | BUILDING | | EXTENSION | |

FOIAb3b

FOIAb3b

| TRANSMITTAL SL - DATE | |
|--|---------|
| то: | |
| ROOM NO. BUILDING | |
| REMARKS: We would preter to | |
| wait to see if there | |
| is any degradation in | |
| the "take" which | FOIAb3b |
| obtained from a test hop | |
| the other day. Also, | |
| LAC is to fly 356 with | |
| its ECM pods on a long profile mission to further | |
| Frotile Mission To turther FROM: | |
| ROOM NO. BUILDING EXTENSION | |
| FORM NO . 241 REPLACES FORM 36-8 #GPO: 1957 - O -439445 WHICH MAY BE USED. | • |